



1/7





3/7





FIG. 3

Transformation Matrix 310

4/7



410

FIG. 4

5/7

	Parameter k1	Parameter k2	Parameter k3
Illuminant A	k1 Value	k2 Value	k3 Value
Illuminant B	k1 Value	k2 Value	k3 Value
Illuminant C	k1 Value	k2 Value	k3 Value
Illuminant D	k1 Value	k2 Value	k3 Value
Illuminant E	k1 Value	k2 Value	k3 Value

Diagram illustrating the Parameter Look Up Table (510). The table has 6 rows (Illuminants A-E) and 4 columns (Parameters k1, k2, k3). Curved arrows point from the column headers to the table cells:
- Column 1 header 'Parameter k1' points to the first column of row 1.
- Column 2 header 'Parameter k2' points to the second column of row 1.
- Column 3 header 'Parameter k3' points to the third column of row 1.
Curved arrows also point from the row numbers to the table cells:
- Row 1 number '534' points to the first column of row 1.
- Row 2 number '538' points to the first column of row 2.
- Row 3 number '542' points to the first column of row 3.
- Row 4 number '514' points to the fourth column of row 2.
- Row 5 number '518' points to the fourth column of row 3.
- Row 6 number '522' points to the fourth column of row 4.
- Row 7 number '526' points to the fourth column of row 5.
- Row 8 number '530' points to the fourth column of row 6.

Parameter Look Up Table: 510

Fig. 5

Camera Gain = 1




FIG. 6

7/7




FIG. 7